ر ٦ Wesleyan University

Capital & Major Maintenance Projects Before & After Photos FY 2020/2021

Capital Projects

Center for Film Studies - Construction of New Addition and Renovation of Existing Building

In Progress




After




Center for Film Studies - Construction of New Addition and Renovation of Existing Building

Before









Center for Film Studies - Construction of New Addition and Renovation of Existing Building

Before





Freeman Athletic Center – New Concession Stand



∖ <u>We</u>sleyan University


Ezzyat Psychology Lab Renovation at Judd 023-030, 207 High Street


Before



ر ٦ Wesleyan University









Padilla-Benavides MBB Lab Renovation at Hall-Atwater 233, 234, 278 – 52 Lawn Avenue

Before





Wesleyan University

٦








Memorial Chapel - Comprehensive Energy 2020 – Lighting Upgrades

Before







<u>Comprehensive Energy 2020 – Lighting Projects</u> Clark Hall / Butterflied A , B, and C Bedroom Ceiling Fixtures

After





CFA L Art Workshops Drawing Studio





Before

After



CFA L Art Workshop Entry Lobby

Major Maintenance FY21 Projects

<u>214 High Street – 2nd Floor Renovation</u>

Before



<u>214 High Street – 2nd Floor Renovation</u>



200 Church Street - Retaining Wall Replacement

Before

After



High Rise Parking Area - Pavement Repairs

Before





After





<u>171 Church St - Fire Alarm Replacement</u>







Before





190 High St - Fire Alarm Replacement

After






<u>1 Vine Street - Fire Alarm Replacement</u>

Before









CFA Theater - Theater/Studios - Design/Studio - Fire Alarm Replacement

Before

After





126 Pearl Street - Fire Alarm Replacement

Before



After



<u>14 Fountain Ave - Electrical Service & Lighting Upgrades</u>











After



∖ <u>We</u>sleyan University

5 Vine Street – Porch Reinforcement

Before





After



<u>5 Vine Street – Foundation/Floor Repair</u>

Before






۲ Wesleyan University






Art Studio North- Roof Replacement


Before



Foss Hill 4 - Concrete Canopy Repair

Before





ر ٦ Wesleyan University










Foss Hill 4 – Roof Replacement

Before



After



162 Church Street Mansard - Roof Replacement


Before











Freeman Athletic Center Hockey Rink – Roof Replacement

Before



ر ۲ Wesleyan University

In Progress





Fauver Upper Apartments - Roof Replacement

Before



After



Van Vleck Observatory - Large Dome Leak Repairs

Before







After








Exley Science Center - Freight Elevator Replacement

Before



After









Judd Hall 2nd Floor – Ceiling & Flooring Replacement

Before










Judd Hall 2nd Floor - Room 218 - New Flooring



ر ۲ Wesleyan University

Judd Hall - 3rd Floor Room 304 & 306 – New Flooring

Before





After



Judd Hall 3rd Floor Corridor - Ceiling Abatement & Replacement

Before






ر ۲ Wesleyan University



95 Pearl Street - Canopy Repair

Before



Undergrad Woodframe Houses - CO Detection Installations

9/11 Brainerd 22/24 Brainerd 32 Brainerd 33 Brainerd 36 Brainerd 57 Brainerd 140 Church 125 Cross 127 Cross 168 Cross 170 Cross 190 Cross 6 Fountain 69A+B Fountain 40 Home

55 Home 81A+B Home 9 Huber 120 Knowles 118 Knowles 55 Lawn 81 Lawn 82 Lawn 42 Miles 207 Pine 211 Pine 215 Pine 223 Pine 235 Pine

265 Pine 273 Pine 277 Pine 19 Vine 21 Vine 2 Warren 14 Warren 25 Fountain 46 Fountain 65 Pearl 151 Church 200 High 203 Pine 343/345 High

Undergrad Wood-Frame Houses - First Floor Structural Reinforcement





ر ۲ <u>We</u>sleyan University

| 1. | 266 Pine | 11. | 159 |
|-----|----------|-----|-----|
| 2. | 76 Lawn | 12. | 163 |
| 3. | 73 Lawn | 13. | 57 |
| 4. | 71 Lawn | 14. | 49 |
| 5. | 65 Lawn | 15. | 44 |
| 6. | 64 Lawn | 16. | 38/ |
| 7. | 55 Lawn | 17. | 36 |
| 8. | 34 Lawn | 18. | 27 |
| 9. | 28 Lawn | 19. | 18/ |
| 10. | 22 Lawn | 20. | 9/1 |

Change -

| 11. | 159 High |
|-----|----------------|
| 12. | 163 High |
| 13. | 57 Brainard |
| 14. | 49 Brainard |
| 15. | 44 Brainard |
| 16. | 38/40 Brainard |
| 17. | 36 Brainard |
| 18. | 27 Brainard |
| 19. | 18/20 Brainard |
| 20. | 9/11 Brainard |







CFA Tunnels- New Insulation Installation

Before




After






247 Pine St – Schonberg Dance Studio – Fire Alarm Panel Upgrade

Before




After




Steam to Hot Water Conversion Phase 1: North Loop CPP to Fisk, CAMS, Pres. House, Boger, CFA

In progress




Steam to Hot Water Conversion Phase 1: North Loop CPP to Fisk, CAMS, Pres. House, Boger, CFA



Boger Hall Heating System Before (Left) and After (Right) - Heating Conversion





After



CPP Chiller Replacement

Before


ر٦

Wesleyan University





In Progress







Freeman Athletic Center Silloway Gym - Floor Refinishing

Before



After





Wood-Frame Houses - New Boiler / Furnace Gas Conversions

Before



ر ۲ Wesleyan University



264 Court Street 170 Cross Street 10A Fountain Ave 40 Fountain Ave 57 Fountain Ave 77 Home Ave After



85 Home Ave
82 Lawn Ave
42 Miles Ave
215B Pine Street
223 Pine Street
239 Pine Street (consolidate hot water into boiler)